

Roof Condition Report

Name: National Retail #000			Job Number:	000-000000-000 Ins	spection Date: <u>12/06/2021</u>			
Address Line1	:							
Building Name	e/Addre	ess Line2:						
City:		Province/State:	Postal/Zip Code:					
Roof Composition								
Roof Section Name A								
Deck:		Metal		Membrane:	PVC			
Insulation:		Polyiso		Surfacing:	None			
Vapor Retarder:		Not known		Resaturated:	No			
Roof Height:		30'		Caulking:	Good			
Approximate Age:		10 Years		Masonry Adjoining:	Good			
Life Remaining:		10 Years		Walls Adjoining:	Good			
Cleanliness:		Good - minor debris		Penetration Flashing:	Good			
Leaking:		No		Fasteners:	Good			
Exposed Areas:		N/A		Drainage & Drains:	Fair, Qty: 20			
Blisters/Ridges:		N/A		Mastic Pans:	N/A			
Splits:		N/A		Skylights:	N/A			
Membrane Flashing:		Good		Roof Mounted Units:	Good, Qty: 22			
Metal Flashing:		Good		Curbs/Sleepers:	Good, Qty: 4			
Work Done and Comments				equired. Cleaned around drains				
Further Work Recommended To fabricate and install one new metal cap flashing where one is currently missing. Main Roof - To clean grease from roof membrane and dispose of as required. Second Roof - To supply and install one new grease catcher as required.								



Roof Condition Report

Name: National Reta	ail #000 Job Number:	000-000000-000 Ins	spection Date: 12/06/2021						
Address Line1:									
Building Name/Address Line2:									
City:	Province/State:	Postal/Zip Code:							
Roof Composition									
Roof Section Name B									
Deck:	Metal	Membrane:	TPO						
Insulation:	Polyiso	Surfacing:	None						
Vapor Retarder:	Not known	Resaturated:	No						
Roof Height:	30'	Caulking:	Good						
Approximate Age:	3 Years	Masonry Adjoining:	Good						
Life Remaining:	10 Years	Walls Adjoining:	Good						
Cleanliness:	Clean	Penetration Flashing:	Good						
Leaking:	No	Fasteners:	Good						
Exposed Areas:	N/A	Drainage & Drains:	Good/Clean, Qty: 4						
Blisters/Ridges:	N/A	Mastic Pans:	N/A						
Splits:	N/A	Skylights:	N/A						
Membrane Flashing:	Good	Roof Mounted Units:	Good, Qty: 7						
Metal Flashing:	Good	Curbs/Sleepers:	Good, Qty: 5						
Work Done and Comments Inspe	cted roof for deficiencies . Cleaned around drains.	Caulked where required. Clear	ned up debris.						